

**BULLETIN NO :** TB-0238  
**DATE :** May 25, 2004  
**TO :** All Fostex Distributors  
**FROM :** Customer Service Department  
**SUBJECT :** PD-6 Software Update to V2.00

---

**MODEL :** PD-6

The PD-6 software has been updated to V2.00 to add and rectify the following points. The WinZip compressed file "PD6V200.zip" is attached together with this bulletin. By extracting the file, a software update file "pd6m200.mot" will be created. Referring to the software update procedures mentioned in the service manual or the technical bulletin # TB-0212 separately, update the PD-6 software accordingly.

Updating the software to V2.00 allows PD-6 to retrofit Model 9056 internal HDD as well as to connect EX12 external drive unit. Since the features and functions will be significantly changed, please refer to the attached V2.0 supplementary manual PDF file for your information.

1. With the software update to V2.00, PD-6 can work with Model 9056 internal HDD option.

**CAUTION 1:** The way to retrofit Model 9056 internal HDD option is mentioned in the service bulletin # SB-0656 issued on May 21, 2004.

2. With the software update to V2.00, PD-6 can work with EX12 external drive unit.

**CAUTION 2:** A memorandum explaining about EX12 external drive unit will be separately issued from our International Sales department. Hardware modifications will be required to connect EX12 to PD-6 with the serial number 0940510 or before. Please refer to the service bulletin separately issued from us shortly.

3. PD-6 with V2.00 software allows to make a MIRROR RECORDING by selecting a dedicated format method.
4. AUTO COPY, DISK COPY and FILE COPY functions have been newly added to V2.00 software.
5. The TC SETUP mode has been newly added and enhanced.

Thank you + best regards,